USEPA 290 BROADWAY NY, NY

NOTIFICATION OF DEMOLITION AND RENOVATION PAL JOB # 16-1609

| Operator Project # | Postmark | Date Received | | | Notification # | | | | |
|---|----------------|----------------------|--|---------|-----------------------------|-------------------|----|--|--|
| TYPE OF NOTIFICATION (O-Original, R-Received, C-Cancelled): O – Original | | | | | | | | | |
| FACILITY INFORMATION (Identify Owner, Removal Contractor and Other Operator): | | | | | | | | | |
| OWNER NAME: 41 Madison LP/Rudin Management Company, Inc. | | | | | | | | | |
| Address: 345 Park Avenue 33 rd Floor | | | | | | | | | |
| City: New York | | | State: NY | | Zip: 10154 | | | | |
| Contact Name: Larry Jaret | | | | Telepho | ephone: 212-407-2400 | | | | |
| REMOVAL CONTRACTOR: PAL Environmental Safety Corp. d/b/a PAL Environmental Services | | | | | | | | | |
| Address: 11-02 Queens Plaza South | | | | | | | | | |
| City: Long Island City | | State: NY Zip: 11101 | | | | | | | |
| Contact Name: Aric Domozick Telephone: 718-349-0900 | | | | | | | | | |
| OTHER CONTRACTOR: | | | | | | | | | |
| Address: | | | | | | | | | |
| City: | | | State: Zip: | | | | | | |
| Contact Name: Telephone: | | | | | | | | | |
| TYPE OF OPERATION (D-Demo, O-Ordered Demo, R-Renovation, E-Emergency Renovation: R | | | | | | | | | |
| IS ASBESTOS PRESENT? (YES NO) YES | | | | | | | | | |
| FACILITY DESCRIPTION (Include Building Name, Number and Floor or Room Number) | | | | | | | | | |
| Building Name: | | | | | | | | | |
| Address: 41 Madison Avenue | | | | | | | | | |
| City: New York | | | State: NY | | | Zip: 10010 | | | |
| Site Location: 9 th Floor Suite 900, Suite 920 & Suite 930 | | | | | | | | | |
| Building Size: 524,937 SF | | | # of Floors: 43 Age in Years: 45 | | | | | | |
| Present Use: Commercial | | | Prior Use: Commercial | | | | | | |
| Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: PLM – Polarized Light Microscopy | | | | | | | | | |
| Approximate amount of asbes | tos , R. ACM | 1 | Non-Friable Indicate Unit of Measurement | | | ent | | | |
| Including | to be | | Asbestos Material | | Below | | | | |
| 1. Regulated ACM to be rem | oved remove | d | not to be removed | | | | | | |
| Category I ACM not remo | | and the second | | | | | | | |
| Category II ACM not remo | oved | | 0.77 | | | | | | |
| | | | CATI | CAT II | | UNIT | | | |
| | | | | L | inear Feet: | Ln M: | | | |
| Surface Area: Spray-on Fire | proofing 5,875 | | | S | quare Feet: | X Square Mete | r: | | |
| Volume RACM off Facility Com | ponent | | | C | ùFt: | Cu M: | | | |
| Scheduled Dates Asbestos Removal (mm/dd./yy) | | | Start: 10/24/2016 | | Complete: 10/01/2017 | | | | |
| Scheduled Dates Demo/Renovation (mm/dd./yy) | | | Start: | | Complete: | | | | |
| | | | | | | v | | | |

| | FARTINE | A TUNN YOUR | | | | | |
|---|-----------|-------------------------|--|--|--|--|--|
| DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD (S) TO BE USED: | | | | | | | |
| DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT | | | | | | | |
| THE DEMOLITION AND RENOVATION SITE: | | | | | | | |
| HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. | | | | | | | |
| WASTE TRANSPORTER #1 | | | | | | | |
| Name: VEOLIA ES Technical Solutions LLC | | | | | | | |
| Address: 1 Edan Lane | 1.00 | | | | | | |
| City: Flanders | State: NJ | Zip: 07836 | | | | | |
| Contact Name: | | Telephone: 973-347-7111 | | | | | |
| WASTE TRANSPORTER #2 | | | | | | | |
| Name: | | | | | | | |
| Address: | | | | | | | |
| City: | State: | Zip: | | | | | |
| Contact Name: | | Telephone: | | | | | |
| WASTE TRANSPORTER #3 | | | | | | | |
| Name: | | | | | | | |
| Location: | | | | | | | |
| City: | State: | City: | | | | | |
| Telephone: | | | | | | | |
| Disposal Facility | | | | | | | |
| Name: VEOLIA ES Technical Solutions LLC | | | | | | | |
| Location: 1 Edan Lane | | | | | | | |
| City: NJ State: Flanders Zip: 07836 | | | | | | | |
| FOR EMERGENCY RENOVATIONS | | | | | | | |
| Date and Hour of Emergency (mm/dd./yy) | | | | | | | |
| Description of the Sudden, Unexpected Event: | | | | | | | |
| Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: | | | | | | | |
| DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY | | | | | | | |
| NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered | | | | | | | |
| unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA | | | | | | | |
| Vacs, to be put in 6 mil poly bags for proper disposal. | | | | | | | |
| I CERTIFY THAT, AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- | | | | | | | |
| SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY | | | | | | | |
| THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) | | | | | | | |
| , 1 | | | | | | | |
| 10/07/2016 | | | | | | | |
| Signature of Owner/Operator Date | | | | | | | |
| I certify that the above information is correct | | | | | | | |
| 10/07/2016 | | | | | | | |
| Signature of D. H. (On our tour | | | | | | | |
| Signature of Owner/Operator Date | | | | | | | |

6 20 10